



658 Southington Road

1801

Captain Stephen Barnes (1769-1801) & Sally Andrews (1771-1857).

colonial

House was originally part of the Ross House located at 708 Southington Road

1985 Townwide Historic and Architectural Survey of Berlin, Connecticut. Survey # 157


1801 Stephen Barnes current owner: Jean Ross

Despite a good deal of later fabric (shingles, sash, and chimney), the Stephen Barnes House is significant as a good surviving example of an early 19th-century vernacular house with a Federal influence apparent in the entry detail. It gains additional significance as a one-bay-deep house, a relatively uncommon building type. Stephen Barnes received this house and land from his father Jonathan in 1801. The entry detailing probably dates to that time, but it is unclear whether Stephen built this house or remodelled it from a small 18th-century dwelling.

2018 Town of Berlin GIS Index.

Sketch

1700 current owner: Wild Flower Crossing LLC



Genealogy

Captain Stephen Barnes (1769-1801) son of Jonathan Barnes & Elizabeth Woodruff. He married Sally Andrews (1771-1857). They had children: Edwin, Truman, Stephen, Eunice, Alvira, Liva. He was a Town Selectman. They are buried in the Blue Hills Cemetery.

HISTORIC RESOURCES INVENTORY BUILDING AND STRUCTURES

HIST-6 NEW 5/77

STATE OF CONNECTICUT
CONNECTICUT HISTORICAL COMMISSION
59 SOUTH PROSPECT STREET, HARTFORD, CONNECTICUT 06106
(203) 566-3005

FOR OFFICE USE ONLY	
Town No.:	Site No.:
UTM:	
QUAD:	
DISTRICT	IF NR, SPECIFY
<input type="checkbox"/> S <input type="checkbox"/> NR	<input type="checkbox"/> Actual <input type="checkbox"/> Potential

IDENTIFICATION		DESCRIPTION	
1. BUILDING NAME (Common)		(Historic) Stephen Barnes House	
2. TOWN/CITY	VILLAGE	COUNTY	
Berlin	Kensington	Hartford	
3. STREET AND NUMBER (and/or location)		19-1 18-1/ 13/34	
658 Southington Road			
4. OWNER(S)		<input type="checkbox"/> Public <input type="checkbox"/> Private	
Ross, Jean E. PO Box 245, Kensington 06037			
5. USE (Present)		(Historic) Residence	
Residence		Residence	
6. ACCESSIBILITY TO PUBLIC:		EXTERIOR VISIBLE FROM PUBLIC ROAD	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
7. STYLE OF BUILDING		DATE OF CONSTRUCTION	
Vernacular		c. 1801	
8. MATERIAL(S) (Indicate use or location when appropriate)			
<input type="checkbox"/> Clapboard <input type="checkbox"/> Asbestos Siding <input type="checkbox"/> Brick <input type="checkbox"/> Other (Specify) _____ <input checked="" type="checkbox"/> Wood Shingle <input type="checkbox"/> Asphalt Siding <input type="checkbox"/> Fieldstone <input type="checkbox"/> Board & Batten <input type="checkbox"/> Stucco <input type="checkbox"/> Cobblestone <input type="checkbox"/> Aluminum Siding <input type="checkbox"/> Concrete Type: _____ <input checked="" type="checkbox"/> Cut stone Type: <u>Brownstone foundation</u>			
9. STRUCTURAL SYSTEM			
<input checked="" type="checkbox"/> Wood frame <input type="checkbox"/> Post and beam <input type="checkbox"/> balloon <input type="checkbox"/> Load bearing masonry <input type="checkbox"/> Structural iron or steel <input type="checkbox"/> Other (Specify) _____			
10. ROOF (Type)			
<input checked="" type="checkbox"/> Gable <input type="checkbox"/> Flat <input type="checkbox"/> Mansard <input type="checkbox"/> Monitor <input type="checkbox"/> sawtooth <input type="checkbox"/> Gambrel <input type="checkbox"/> Shed <input type="checkbox"/> Hip <input type="checkbox"/> Round <input type="checkbox"/> Other (Specify) _____ (Material) <input type="checkbox"/> Wood Shingle <input type="checkbox"/> Roll Asphalt <input type="checkbox"/> Tin <input type="checkbox"/> Slate <input type="checkbox"/> Gable end to the street <input checked="" type="checkbox"/> Asphalt shingle <input type="checkbox"/> Built up <input type="checkbox"/> Tile <input type="checkbox"/> Other (Specify) _____ <input checked="" type="checkbox"/> Ridge parallel to the street			
11. NUMBER OF STORIES		APPROXIMATE DIMENSIONS	
2		34' x 17'	
12. CONDITION (Structural)			
<input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated <input type="checkbox"/> Excellent <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Deteriorated			
13. INTEGRITY (Location)			
<input checked="" type="checkbox"/> On original site <input type="checkbox"/> Moved <input type="checkbox"/> WHEN? (Alterations) <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No IF YES, EXPLAIN New exterior brick chimney, shingles			
14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES			
<input type="checkbox"/> Barn <input type="checkbox"/> Shed <input checked="" type="checkbox"/> Garage <input type="checkbox"/> Other landscape features or buildings (Specify) _____ <input type="checkbox"/> Carriage house <input type="checkbox"/> Shop <input type="checkbox"/> Garden			
15. SURROUNDING ENVIRONMENT			
<input type="checkbox"/> Open land <input type="checkbox"/> Wood-land <input checked="" type="checkbox"/> Residential <input checked="" type="checkbox"/> Scattered buildings visible from site <input type="checkbox"/> Commercial <input type="checkbox"/> Industrial <input type="checkbox"/> Rural <input type="checkbox"/> High building density			
16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS			
Surrounded by low-density modern housing.			

157

DESCRIPTION (Continued)	17. OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and/or exterior)	
	<p>The Stephen Barnes House has a five-bay facade and a central entry. Entry detailing is largely old or original, and features plain pilasters with denticular capitals and a radial-glazed semi-circular fanlight with wooden muntins. A slightly projecting gabled entry hood has large plumb-cut dentils under the rakes and a partial return of the molded cornice. The six-paneled entry door is also old or original. Windows have molded surrounds and are fitted with 2-over-2 sash. Facade windows are located immediately under the eaves. The house is only one bay deep, the left elevation has a later exterior brick chimney, there is a side entry on the right elevation.</p>	
SIGNIFICANCE	18. ARCHITECT	BUILDER
	<p>19. HISTORICAL OR ARCHITECTURAL IMPORTANCE</p> <p>Despite a good deal of later fabric (shingles, sash, and chimney), the Stephen Barnes House is significant as a good surviving example of an early 19th-century vernacular house with a Federal influence apparent in the entry detail. It gains additional significance as a one-bay-deep house, a relatively uncommon building type. Stephen Barnes received this house and land from his father Jonathan in 1801. The entry detailing probably dates to that time, but it is unclear whether Stephen built this house or remodelled it from a small 18th-century dwelling.</p>	
SOURCES	<p>1855 Atlas 1869 Atlas Berlin Land Records 3:385 (1801)</p>	
PHOTO	<p>PHOTOGRAPHER HRC</p> <p>VIEW NE</p>	<p>DATE 11/84</p> <p>NEGATIVE ON FILE G27</p>
	<p>COMPILED BY Historic Resource Consultants The Colt Armory 55 Van Dyke Avenue Hartford, Connecticut 06108</p>	
20. SUBSEQUENT FIELD EVALUATIONS		

